



Suite 201, 1090 King Georges Post Road,  
Edison, NJ 08837 • (201) 225-6116

TECHNICAL ASSISTANCE TEAM FOR EMERGENCY RESPONSE REMOVAL AND PREVENTION  
EPA CONTRACT 68-01-7367

TO: C. FITZSIMMONS  
FROM: J. MANFREDA  
SUBJECT: Documentation of Transmittal  
SITE: L/ACO-SPEC  
TDD#: 2-8801-42  
DATE: 2/2/88

The purpose of this memo is to document the transmittal of  
the following:

☒ Letter Report DCN# 02-F-04415  
☐ OSC Report Draft/Final DCN# \_\_\_\_\_  
☐ Photographs  
☐ Analytical Data  
☐ POLREP  
☐ Safety Plan DCN# \_\_\_\_\_  
☐ Community Relations Plan DCN# \_\_\_\_\_  
☐ Sampling Plan DCN# \_\_\_\_\_  
☐ Sampling Report DCN# \_\_\_\_\_  
☐ Action Memorandum DCN# \_\_\_\_\_  
☐ SPCC Report  
☐ Site Maps  
☐ Other \_\_\_\_\_

cc: TAT PM  
TDD File

Roy F. Weston, Inc.

SPILL PREVENTION & EMERGENCY RESPONSE DIVISION

In Association with ICF Technology Inc., C.C. Johnson & Associates, Inc., Resource Applications, Inc.,  
Geo/Resource Consultants, Inc., and Environmental Toxicology International, Inc.

333566





Suite 201, 1090 King Georges Post Road,  
Edison, NJ 08837 • (201) 225-6116

TECHNICAL ASSISTANCE TEAM FOR EMERGENCY RESPONSE REMOVAL AND PREVENTION  
EPA CONTRACT 68-01-7367

TAT-02-F-04415

MEMORANDUM

TO: Charles Fitzsimmons  
Response and Prevention Branch, U.S. EPA

FROM: James Manfreda, TAT II *JM*  
John Brzozowski, TAT II QC

SUBJECT: LILCO Non-compliance Facilities

DATE: February 1, 1988

In accordance with TDD# 8801-42, the LILCO facilities listed below were previously inspected and found to be in non-compliance:

- 1) Port Jefferson
  - a) Requires upgrading of tank truck unloading facilities
  - b) Requires lining of secondary containment floor areas
- 2) Glenwood Landing
  - a) Requires upgrading of tank truck unloading facilities
  - b) Requires lining of secondary containment floor areas
- 3) West Babylon - *In good condition*
  - ☒ a) Requires upgrading of tank truck unloading facilities
  - ☒ b) Requires lining of secondary containment floor areas
- 4) Northport
  - a) Requires upgrading of tank truck unloading facilities
  - b) Requires lining of secondary containment floor areas

Roy F. Weston, Inc.

SPILL PREVENTION & EMERGENCY RESPONSE DIVISION

In Association with ICF Technology, Inc., C.C. Johnson & Malhotra, P.C., Resource Applications, Inc.,  
Geo/Resource Consultants, Inc., and Environmental Toxicology International, Inc.

5) Shoreham

- a) Requires upgrading of truck unloading area

6) Far Rockaway

- a) Facility was in cold standby status at time of inspection and should be inspected if in operation

Mr. Charles Mazzilli, Environmental Engineer of LILCO was contacted on February 1, 1988 in reference to inspecting the facilities during week of February 8th or 15th. Mr. Mazzilli suggested the week of February 15th for conducting the inspections. I will notify him on February 12th to set-up for the inspection schedule.